

FTD WORK ORDER

Date Issued 23 Dec 1968

1. Description of Work: (Include title of unscheduled tasks.)

Request photo analysis be accomplished on the attached photograph to determine what the unidentified flying object may be.

19 Nov 68, near Acton, Texas.

Request all material be returned upon completion of analysis.

-FROM-

- 2. FTD W.O. No.
- 3. Monitor
- I Col Cuintanilla 4. Office Symbol/Ext.
 - (1 0)/70916
- 5. DIA Task No.
- 165-01-39
- 6. DIA Priority/FTD Preced.
- 7. Date Needed
- 8. Date Completed
- 9. Classification of Sources
 - /11 Termes
- 10. Classification of End Product
 - Use La sified
- 11. Apprv. Sig.

18. Div. Chiefs Instructions/Modification or Expansion of Work Description

-TO-

- 12. Br. Off. Sym/Func No.
- 13. M-H Estimpte
- 14. Contributor
- 15. Phones
- 16. Prec./Revision Date
- 17. Branch Chf/Div. Sig.

31 Dec 68

Copy No. 2

FTD JUN 68 13

Previous edition of this form is obsolete.

DEPARTMENT OF THE AIR FORCE HEADQUARTERS UNITED STATES AIR FORCE WASHINGTON, D.C.



P.O. Box 1689, Ft Worth, Tex 76101

SUBJECT: UFO Photograph of 19 Nov 68, near Acton, TX (Your 1tr, 13 Dec 68)

16 December 1968

TO: FGN TEC DIV (TDPT (UFO))

1. Attached is photograph negative requested by your letter of 13 Dec 68.

2. Please return the negative to this Office upon completion of your analysis.

RAY P. CARTER, Lt Col, USAF

Air Force Representative

FAA SW Region

1 Atch

Photo Negative

Underwrite Your Country's Might - Buy U.S. Savings Bonds

TDPT (UFO)

WFO photograph of 19 November 1968 near Action, Texas

Air Force Representive FAA, Southwest Region (SW-900) Fort Worth, Texas

13 DEC 1968

Lt Col Carter

Reference letter of 5 December 1968. We would like to submitt
Mr Frund's photograph to our own photo-experts. We would apprecate it if you would have him submitt the original negative of the photograph showing the UFO to our office here at Wright-Patterson AFB.

MECTOR QUINTANILLA, Jr, Lt Colonel, USAF Chief, Aerial Phenomena Branch Aerospace Technologies Division Production Directorate F"O"R" O"F"F"I"O"T"A" DOWN BELLEVO NULL ON BELLEVO

DEPARTMENT OF THE AIR FORCE HEADQUARTERS UNITED STATES AIR FORCE WASHINGTON, D.C.



P.O. Box 1689, Ft Worth, Tex 76101

SUBJECT: Possible UFO Sighting

5 December 1968

то: FTD (TDETR) Wright Patterson AFB OH 45433

- 1. The attached letter and enclosures are forwarded for your information and possible action in accordance with AFR 80-17.
- 2. As indicated in paragraph two of attachment, the photographer is available for interview if this should be deemed necessary.

FOR THE CHIEF OF STAFF

RAY P. CARTER, Lt Col, USAF Air Force Representative

FAA SW Region


1 Atch Ltr, FAA SW Rgn, Engineering Photographs, 5 Dec 68


FOR OFFICIAL USE WOODS

Underwrite Your Country's Might - Buy U.S. Savings Bonds


CARTO














DEPARTMENT OF TRANSPORTATION FEDERAL AVIATION ADMINISTRATION

DATE: December 5, 1968

SOUTHWEST REGION P. O. BOX 1689 FORT WORTH, TEXAS 76101

IN REPLY SW-90

SUBJECT: Engineering photographs



TO: Air Force Representative FAA, Southwest Region (SW-900)

The enclosed photographs were taken by Mr. Paul H. Freund, civil engineer with the FAA, Southwest Region, Fort Worth, Texas. The photographs were taken on November 19, 1968, in connection with the location of a navigational aid facility approximately 1½ airline miles southeast of Acton, Texas. The pictures are numbered on the back in the sequence taken, time taken approximately 2:30 P.M.; and all eight shots were taken in a period of thirty to forty-five minutes, which means the shots were taken between the times of approximately 2:30 and 3:30 P.M.


The first shot Number 12-1, we feel, may be of interest to you and was taken from our engineering station 7 + 62 of the proposed access road on a bearing S 11° W, latitude 32° 26′ 10″, longitude 97° 39′ 49″, using a Kodak Tourist II 620 camera at exposure 1/100 second at F 16 using Verichrome pan film. The person taking the pictures was unaware of the object shown close to the horizon and can offer no explanation as to what it might be. The photographers processing the film are unable to explain the object or how it came to be depicted on the print. They first thought that it was a flaw in the negative but determined this was not the case. They therefore made the two blown up prints of this picture. Individual field notes, the photographic negatives, and the person who took the shots are available in the event further information is desired.


As we discussed, it is requested that you forward these items to the proper authorities for action deemed appropriate. We would appreciate being apprised of any action and the results thereof.

JOHN C. ADAMS

Chief, Compliance and Security Division, SW-90

Enclosures







1 - 31 DECEMBER 1968 SIGHTINGS

DATE	LOCATION
Dec	Memphis, Tennessee
3	'Greenfield, Iowa
5	Helena, Arkansas
5	Bellefontaine, Ohio .
3 5 5 6	Dayton, Ohio
8	(Centerville, Ohio
11	Clayton, Alabama
12	WGermantown, Tennessee
14	'Iowa City, Iowa
15	'St Louis, Montana
15	/Palmyra, Michigan
16	'Morgantown, West Virginia
17	Williams, Minnesota
23	'Saratoga, California
28	Manchester, Pennsylvania
30	Natrona, Pennsylvania
31	New Carlisle, Indiana



EVALUATION

Other (CONFLICTING DATA) Aircraft Balloon Other (UNRELIABLE REPORT) Aircraft Astro (VENUS) Balloon Aircraft Satellite Balloon Balloon Astro (VENUS) Insufficient Data Aircraft Other (CONFLICTING DATA) Satellite Other (CONFUSING DATA)

ADDITIONAL REPORTED SIGHTINGS (NOT CASES)

DATE	LOCATION		
-	-United States		
A STATE OF THE PARTY OF THE PAR	United States		
1.0	iFt Recovery, Ohio		
11	Aceland		
30	r Panama		

NICAP NICAP Memo Ltr Msg

EVALUATION

THIS CASE INCLUDES

· 1 PHOTOS 5X8

TDPT (UFO)

UFO Photograph of 19 Nov 68 Near Acton, Texas

Mr. John C. Adams
Chief, Compliance & Security Division, SW-90
P. O. Box 1689
Fort Worth, Texas 76101

- 1. Reference the UFO photograph taken by Mr. Paul H. Freund on 19 Nov 68 near Acton, Texas. Photographic analysis of the negative has been completed by our photo analysts. The results of their findings are as follows:
- a. Examination and technical analysis of the print and corresponding negative furnished by Lieutenant Colonel Carter indicate that the most probable explanation of the image in question is that it is a film processing or emulsion defect. One evident possible cause is she abnormal appearance of the emulsion side of the negative at the location of the image in question. There appears to be some form of foreign substance of high reflectivity covering the area around the image. The "spot" would be impossible to analyze without destroying the image in question. It appears as though there may have been a chemical deposit on or in the emulsion which prevented exposure in that area and then retarded development when it was dissolved by the processing liquids. Corroboration of this explanation might have been accomplished if the film wrapper had been available for analysis.
- b. Facts concerning the exposure of the film on which image in question appears, tend to confirm the probability that the "object" is a result of physical phenomena occurring within the camera. The facts are as follows:
 - (1) The photographer did not actually see the "object".
- (2) Eight photos were made (the assumption is made that more than one photo covers the same general area) but the "Object" appears on only one photo.

2. The referenced photographic negative which you loaned to Lt Col Carter is enclosed. Thank you for your patience and cooperation.

Chief, Aerial Phenomena Office
Aerospace Technologies Division
Production Directorate

1 Atch Negative

PHOTO ANALYSIS REPORT

69-19

PAGE | OF ____ PAGES DATE OF REPORT 29 October 1969

SUBJECT	UNIDENTIFIED FLYING OBJECT		
LOCATION	Acton, Texas	DATE	19 November 1958
	PHOTOG	RAPHY	

AF		IR	QUALITY Fair	
P NRS	One 2½x3½ ne	ative and 8x10 B&W prin	nt enlargement	•

1. PURPOSE: This report is in response to Work Order Number 68-110 submitted by Lieutenant Colonel Quintanilla (TDPT) requesting analysis of a photograph taken near Acton, Texas, 19 November 1968, to determine the identity of a purported UFO.

2. ANALYSIS:

- a. Examination and technical analysis of the print and corresponding negative furnished by Lieutenant Colonel Carter indicate that the most probable explanation of the image in question is that it is a film processing or emulsion defect. One evident possible cause is the abnormal appearance of the emulsion side of the negative at the location of the image in question. There appears to be some form of foreign substance of high reflectivity covering the area around the image. The "spot" would be impossible to analyze without destroying the image in question. It appears as though there may have been a chemical deposit on or in the emulsion which prevented exposure in that area and then retarded development when it was dissolved by the processing liquids. Corroboration of this explanation might have been accomplished if the film wrapper had been available for analysis.
- b. Facts concerning the exposure of the film on which image in question appears, tend to confirm the probability that the "object" is the result of physical phenomena occurring within the camera. The facts are as follows:
 - (1) The photographer did not actually see the "object".
- (2) Eight photos were made (the assumption is made that more than one photo covers the same general area) but the "object" appears on only one photo.

PHOTO ANALYSIS BY:

JOHN W. SUMMERFIELD Specialist

Thomas Evans, THOMAS E. DAVIS

Intelligence Research Specialist

APPROVED BY:

William Column

WILLIAM L. TURNER

Chief, Photo Analysis Branch

WILBER PRICE, JR.

Chief, Photo Exploitation Division

CHARLES E. CHAPIN Photographic Technologist

bjb

UNCLASSIFIED

DEPARTMENT OF THE AIR FORCE HEADQUARTERS UNITED STATES AIR FORCE WASHINGTON, D.C.



P.O. Box 1689, Ft Worth, Tex 76101

SUBJECT: UFO Photograph of 19 Nov 68, near Acton, Texas (Your Ltr, 17 Jan 69)

23 January 1969

TO: FGN TEC DIV (TDPT (UFO))

- 1. The Chief of Compliance and Security, FAA SW Region prefers that your Photo Analysis Section complete their analysis of the negatives.
- 2. As stated previously, request this Office be furnished a copy of the analysis when the negatives are returned.

FOR THE CHIEF OF STAFF

LARAY P. CARTER, Lt Col, USAF

Air Force Representative

FAA SW Region

Copy to: SW-90, FAA SW Rgn (Mr. Adams)

Underwrite Your Country's Might - Buy U.S. Savings Bonds

TDPT (UFO)

UFO Photograph of 19 Nov 68, near Acton, Texas

Lt. Col. Ray P. Carter
USAF Representative
FAA SW Region
P.O. Lox 1689
Fort Worth, Texas 76101

Reference your letter of 13 Jan 1969. The negatives for the 19 Nov 68, Acton, Texas photos have been submitted to the FTD photo analysis section. However, because UFO photographs are handled on a low priority basis, the analysis has not been completed yet. If the observer wants his negatives back immediately, we can return them before the analysis is completed; however, due to higher priority work, the analysis of the negative may take several months yet. Request you notify us of the decision of the observer or have the observer notify us of his decision.

FOR THE COMMANDER

HECTOR QUINTANILLA, Jr, Lt Colonel, USAF Chief, Aerial Phenomena Branch Aerospace Technologies Division Production Directorate

DEPARTMENT OF THE AIR FORCE HEADQUARTERS UNITED STATES AIR FORCE WASHINGTON, D.C.



REPLY TO

USAF Representative, FAA SW Region P.O. Box 1689, Ft Worth, Tex 76101

SUBJECT:

UFO Photograph of 19 Nov 68, near Acton, TX (Your 1tr 13 Dec 68; my 1tr 16 Dec 68)

13 January 1969

TO: FGN TEC DIV (TDPT (UFO))

1. In response to your letter of 13 December 1968, we forwarded the original negative of a photograph showing an "unidentified flying object" near Acton, Texas. The photographs and the negative were obtained from the Security Division, FAA Southwest Region with the provision that the negative would be returned.

2. The FAA has asked that we contact you and request return of the negative. Also, they desire comments regarding your analysis of the negative.

RAY PA CARTER, Lt Col, USAF

Air Force Representative

FAA SW Region

Copy to: FAA SW Rgn (SW-90/Mr. Adams)

Underwrite Your Country's Might - Buy U.S. Savings Bonds